

Forest Lakes Mutual Water Company has completed the initial lead service line inventory required by U.S. EPA's Lead and Copper Rule Revisions. The deadline for the initial inventories was October 16, 2024.

Through completing field investigations, Forest Lakes Mutual Water Company has determined it has no lead or galvanized requiring replacement service lines in its distribution system. This includes any privately-owned or customer-owned service lines.

Forest Lakes Mutual Water Company reviewed all applicable sources of information, including

- All inspections and records of the distribution system that indicate service line material, including inspections conducted during the course of normal operations (e.g., checking service line materials when reading water meters or performing maintenance activities); and

In addition to reviewing the above sources of information, Forest Lakes Mutual Water Company physically inspected all service lines in its distribution system, regardless of ownership. All service lines were verified non-lead.

Forest Lakes Mutual Water Company
2024 Lead & Copper Line Survey by Shareholder ID

Forest Lakes Mutual Water Company
2024 Lead & Copper Line Survey by Shareholder ID

Forest Lakes Mutual Water Company
2024 Lead & Copper Line Survey by Shareholder ID

Forest Lakes Mutual Water Company
2024 Lead & Copper Line Survey by Shareholder ID

Forest Lakes Mutual Water Company
2024 Lead & Copper Line Survey by Shareholder ID